

Play Equipment Inspection Report

Name S.Coates
Date 23/07/2026

		Item Description/Name	Satisfactory	Not Satisfactory	Hazard	Risk (L/M/H)	Recommended Action
Covingham Park	Skate Park	General Surfacing	✓				
		Seats/Benches	✓				
		Bin	✓				
		Signage	✓				
		Quarter Pipe	✓				
		Flat Ramp	✓				
		Wave Ramp	✓				
		Fun Box with steps	✓				
		Full Pyramid	✓				
		Straight Grind Rail (1)	✓				
		Straight Grind Rail (2)	✓				
	Toddler Play Area	General Surfacing	✓			L	2 x Slight damage to surface
		Seats/Benches	✓				
		Bin	✓				
		Gates & Entrance	✓				
		Perimeter Fencing	✓				
		Signage	✓				
		The Cloud	✓				
		Rock 'n' Bowl	✓				
		Rocker Yellow	✓				
		Double Swing	✓				
	Junior Play Area	General Surfacing	✓			L	Small damage to surface
		Seats/Benches	✓				
		Gates & Entrance	✓				
		Perimeter Fencing	✓				
		Signage	✓				
		Gaheris' Castle Multiplay unit	✓				
		Flymobile Roundabout	✓				
		Buddy Board	✓				
		Double Swing	✓				
	MUGA	General Surface	✓				
		Fences	✓				
		Signage	✓				
		MUGA walls	✓				
	Adult Exercise Equipment	General Surface (matting/grass)	✓			L	Some areas still to be levelled up
		Signage	✓				
		Steps	✓			L	to be painted
		Cross Rider	x				
		Rower	✓				
		Cycle	✓			L	1 bearing worn - monitor
		Air Walker	✓			L	1 bearing worn - monitor
		Skier	✓				
		Body Twist	✓				
		Rider	✓				
		Chest Press	✓				
Smittenbrook Park	Basket Ball Court	General Surface	✓				
		Signage	✓				
		Basket Ball Post (1)	✓				
		Basket Ball Post (2)	✓				