

Play Equipment Inspection Report

Name S.Coates
Date 18/03/2026

		Item Description/Name	Satisfactory	Not Satisfactory	Hazard	Risk (L/M/H)	Recommended Action	
Covingham Park	Skate Park	General Surfacing	√					
		Seats/Benches	√					
		Bin	√					
		Signage	√					
		Quarter Pipe	√					
		Flat Ramp	√					
		Wave Ramp	√					
		Fun Box with steps	√					
		Full Pyramid	√					
		Straight Grind Rail (1)	√					
	Straight Grind Rail (2)	√						
	Toddler Play Area	General Surfacing	√				L	Slight damage to surface next to rocker
		Seats/Benches	√					
		Bin	√					
		Gates & Entrance	√					
		Perimeter Fencing	√					
		Signage	√					
		The Cloud	√					
		Rock 'n' Bowl	√					
		Rocker Yellow	√					
	Double Swing	√						
	Junior Play Area	General Surfacing	√				L	Small damage to surface
		Seats/Benches	√					
		Gates & Entrance	√					
		Perimeter Fencing	√					
		Signage	√					
		Gaheris' Castle Multiplay unit	√					
		Flymobile Roundabout	√					
		Buddy Board	√					
	Double Swing	√						
	MUGA	General Surface	√					
		Fences	√					
		Signage	√					
		MUGA walls	√					
Adult Exercise Equipment	General Surface (matting/grass)	√				L	To be levelled in the spring	
	Signage	√						
	Steps	√				L	to be painted	
	Cross Rider	x						
	Rower	√						
	Cycle	√						
	Air Walker	√						
	Skier	√						
	Body Twist	√						
	Rider	√						
Chest Press	√							
Smittenbrook Park	Basket Ball Court	General Surface	√					
		Signage	√					
		Basket Ball Post (1)	√					
		Basket Ball Post (2)	√					